Service Entry



3 Option 1: Type the number or name of the vehicle.



4 Option 2: Click the vehicle directly from the vehicle list.

	Contact Reliewais					
.0	Service 🔻	CAR VEH-0246	2015	CLUB CAR	Carryall 710 LSV	5J5LC22B0GA618467
	Service History	CAR VEH-0247	2015	CLUB CAR	Carryall 710 LSV	5J5LC22B7GA618496
	Service Programs	VEH-0262	2016	CHEVROLET	MALIBU	1G1ZJ5SU1GF281193
	Shop Directory	VEH-0296	2019	CHEVROLET	COLORADO	1GCGSCEN4K1314794
2	Contacts	🗌 🏹 VEH-0313	2022	CLUB CAR	Carryall 700 LSV	A5CUBB2DHNA30765
	Fuel & Energy >	VEH-0315	2018	CHEVROLET	SUBURBAN	1GNSKGKC4JR136977
•	Places					

5	Click "Add"	,					
						Q ¹⁴ ③	+
				E	R+ Q Watch ····	🔁 Edit 🕇 🕇	- bt
gement	Tire Activity	Service Reminders	Renewal	Reminders Issu	es More Y	🗟 Perso	onalize
		+ Add Issue	View All	Comments			l>
	Open <mark>1</mark>			4	@Matt, your truck is ready to g	o.	¢
by <u>Test Test</u> on passenge	er side.	O Resolve	• ••		Shannon S.		C <mark>.</mark>

6	Click "Add	Service Entry"					
						نۍ نۍ	/ т
				EL &	Q	Watch 💼 Edit +	Add 🗸
						Add Vehicle Assignment	Q+
						Add Fuel Entry	Ð
ement	Tire Activity	Service Reminders	Renewal R	leminders Issues	5 N	Add Expense Entry	٥
		+ Add Issue	View All	Comments		Add Service Entry	S
		T Add Issue	VIEW AII			Add Issue	≙
	Open					Add Inspection Submission	6
	1				@Matt,	Add Work Order	=
					(Add Warranty	0
Test Test		⊘ Resolve •	/		(Add Service Reminder	6
passenge	er side.				(Add Vehicle Renewal Reminder	6

7	Select the	appropriate	Repair Priority	/ Class
-				,

Vehicle *
VEH-0315
Repair Priority Class
Please select
Emergency Completion Date *
🔁 03/10/2024 🔘 🛈 11:38am
Set Start Date

8 Enter the vehicle mileage in the Odometer box.

Vehicle *	
VEH-0315	
Repair Priority Class	
Non-Scheduled	
Repair Priority Class (VMRS Code Key 16) is a simp Odometer * Last updated: 104,703 mi (Today) Completion Date *	ni <u>Void</u>
₿ 03/10/2024	🕚 11:38am
Set Start Date	
Reference	

9 Add the date and time the repairs were completed.

Repair Priority Class	
Non-Scheduled	
Repair Priority Class (VMRS Code Key 16) is a simple way to classify whether a service or repair was schedu Odometer *	ie
104707 mi <u>Void</u>	
Last updated: 104,703 mi (Today)	
Completion Date *	
🔁 03/10/2024 🕥 11:38am	
Set Start Date	
Reference	
Vendor	
Please select	
Labels	

10 Select the supplier who performed the service. If not listed, create new.

Reference
Vendor
Please select
Lake Country Chevrolet/Silsbee 2152 N Wheeler St, Jasper, Texas 75951, US Metro Golf Cars Inc 4063 South Fwy, Fort Worth, Texas 76110, US
Sewell 5100 Bryant Irvin Rd, Fort Worth, Texas 76132, US Texas Christian University 2800 S University Dr, Fort Worth, Texas 76109, US
③ Select any issues that were resolved as part of this service

11 Add the item repaired and select from the dropdown list.

ine Items			View Servio
Q windshield			
ALL			
Windshield Chip Repair 🖪			
Windshield Replacement			
Windshield Washer Fluid Fill 🛽			
Windshield Washer Fluid Level Inspect 💿			
Windshield Washer System Inspect S			
Windshield Wiper Blade Inspect 💿			
Windshield Wiper Blade Replacement 🖻			
	<u>li</u>	Subtotal	

12 If this repair is related to a vehicle 'Issue', click "Link Issues"

Q Search Service Tasks				101
80 ≹		Labor	Parts	Subtota
 Windshield Replacement I 		\$0.00	\$0.00	\$0.0
D Last Completed: Never				
Link Issues				
Add notes or additional details				
MAINTENANCE CATEGORIZATION ▼				
Reason for Repair 🗿	Category / System / Assembly 🗿			
Select Reason for Renair	0 - Cab, Climate Contr V	002 - Cab & Sheet Metal 🗸	024 - Glass	

13 Select the Issue related to this repair.

у	Link Issues	×
	Service Task Windshield Replacement	
	#11 Windshield Cracked Hail caused crack in windshield on passenger side.	
		Cancel Save atus
	Medium #11 Windshield Cracked	+ Link to Line Items Open
	Line Items 1	

14 Click "Save"

	+ Add Issue
ld Cracked	
e crack in windshield on passenger side.	
	Cancel Save atus Labels Assigned Work Or
indshield Cracked	+ Link to Line Items Open — — —
	View Service Reminders 10
	😅 Customize

Add the amount for labor.

				Þ
			View	Service Reminders 10
Tasks				😅 Customize
		Labor	Parts	Subtotal
Replacement	▲1	\$0.00	\$0.00	\$0.00
ted: Never				
es				
r additional details				le la
CATEGORIZATION 🔻				
pair 0	Category / System / Assembly 📀			

Add the amount for parts.

v Service Reminders 10	Viev		
😴 Customize			
Subtotal	Parts	Labor	
\$105.00	\$0.00	s 10\$	1

 Windshield Replacement
MAINTENANCE CATEGORIZATION Reason for Repair Category / System / Assembly Select Reason for Repair 0 - Cab. Climate Contr 002 - Cab & Sheet Metal 024 - Glass
LINKED ISSUES (1) #11 · Windshield Cracked ③

18 Select the most appropriate reason from the dropdown.

	Please select]
	05 Inspection, Routine 🖪	A
_	08 Preventive Maintenance 🖪	
Gene	13 No Start S	Cost Summary
Add	15 Accessories S	Labor
	16 Worn Out S	Deste:
	23 Modification S	Parts
	31 Accident, Non-Reported 🖸	Subtotai
	32 Accident, Reported	Credits
	45 Damage S	Discount 🛈 🦷 🕺
	47 Abuse Caused by Driver 🖸	Tax %
	56 Campus Department Charge Back	

Add notes related to this repair, if any.

LINKED ISSUES (1) 🔻	
#11 · Windshield Cracked 💿	
Hail caused crack in windshield on passenger side.	
General Notes	Cost Summary
Add notes additional details	Labor
And hores of auditional details	Labor
	Parts
	Subtotal
	Warranty Credits
	Discount ① % ~ 0
	Tax % 🗸

20 Add photos, if any.		
		Ιdλ
		Tota
	Photos	Documents
	+ Drag and drop files to upload or click to pick files	+
	Comments	
	Add an optional comment	

Add repair invoice.

	Tax % 🗸	\$0.00
	Total	\$667.00
	Documents	
op files to upload files	+ Drag and drop fi or click to pick files	les to upload
t		

22 Add comments, if any.

Photos + Drag and drop files to upload or click to pick files	Documents +
Comments Add an optional comment Cancel	
Cancer	

Documents	
+ Drag and drop files to upload or click to pick files	
·/	
Save & Add Another Save Service Entry	
	Documents Drag and drop files to upload or click to pick files Save & Add Another

24 Occasionally the mileage will show an error message. Modify mileage to the range required.

Details
Vehicle *
VEH-0315
Repair Priority Class
Non-Scheduled
Repair Priority Class (VMRS Code Key 16) is a simple way to classify whether a service or re Odometer * 104707 mi Void must be between 104,702 and 104,703 or marked as void Last updated: 104,703 mi (Today) Completion Date *
🖆 03/06/2024 🕥 12:00pm
Set Start Date
Reference

25	Click "Save Service Entry"
----	----------------------------

Documents	
Drag and drop files to upload or click to pick files	
Save & Add Another Save Service Entry	l.